Gigabit board is not working properly on MIPS 2000 series servers

Published 12/12/2011

Symptom(s):

Gigabit board is not working properly on MIPS 2000 series servers

Fact(s):

SGI 2200 Deskside server
SGI P/N 9210292: PCIX-GIGENET-C-2P

SGI Solution:

Contact SGI sales for a compatible card.

Cause(s):

Unsupported card for MIPS based 2000 series

Additional Details

Creation Date	12/09/2011 10:13 AM
Last modification	01/15/2016 04:29 PM
Published Date	12/12/2011
Products	• Servers and Clusters • SGI Origin/Onyx • Origin/Onyx Server • Peripherals • Networking • Ethernet NIC • Ethernet Switch • Switches and Cables • Workstations • SGI Tezro • O2 • Octane
Categories	• Knowledgebase • Technical Solution